



HELMETS MEASURING GUIDES

- TFX
- ICE
- CC2 / 2X / 2,5X / 3X / SPEED

TFX HELMET MEASURING GUIDE



Measure the circumference of the head at the forehead height, being careful that the tape is horizontal and has the right tension (not too loose, not too tight)

HEAD CIRCUMFERENCE

1



Extend the tape measure around the face, being careful to pass it on top of the chin, above the ears up to the top back of the head.

FACE CIRCUMFERENCE

2



Measure the face width by positioning 2 rulers (or similar objects), at the base of the ears and make sure they are hold vertically and parallel between them. Extend the tape horizontally and measure the distance between the 2 points.

If possible, kindly provide picture of measurement 3 taken; it will ease the online fitting process and ensure more accurate custom fit of the helmet.
Note: the picture upload is not mandatory.

FACE WIDTH

3



ICE HELMET MEASURING GUIDE



Measure the circumference of the head at the forehead height, being careful that the tape is horizontal and has the right tension (not too loose, not too tight)

HEAD CIRCUMFERENCE

1



Measure the face width by positioning 2 rulers (or similar objects), at the base of the ears and make sure they are hold vertically and parallel between them. Extend the tape horizontally and measure the distance between the 2 points.

If possible, kindly provide picture of measurement 2 taken; it will ease the online fitting process and ensure more accurate custom fit of the helmet.
Note: the picture upload is not mandatory.

FACE WIDTH

2



HELMET MEASURING GUIDE



Measure the circumference of the head at the forehead height, being careful that the tape is horizontal and has the right tension (not too loose, not too tight)

HEAD CIRCUMFERENCE

1